


Tree Caps and Tees/Crosses

BHTA

Flange Size	Working Pressure	Lift Threads	Bore	Part Number
2-1/16"	5,000	2-3/8" Up Tbg	2-1/16"	
2-1/16"	10,000	2-3/8" Up Tbg	2-1/16"	
2-9/16"	5,000	2-7/8" Up Tbg	2-9/16"	
2-9/16"	10,000	2-7/8" Up Tbg	2-9/16"	



Tees

Run Size	Working Pressure	Outlet Size	Working Pressure	A	B	C	D	Part Number
2-1/16"	5,000	2-1/16"	5,000	4.50"	4.50"	2.06"	2.06"	
2-9/16"	5,000	2-1/16"	5,000	4.50"	5.00"	2.56"	2.06"	
2-1/16"	10,000	1-13/16"	10,000	4.38"	4.38"	2.06"	1.81"	
2-9/16"	10,000	1-13/16"	10,000	4.50"	5.12"	2.56"	1.81"	
4-1/16"	10,000	1-13/16"	10,000	6.875"	6.875"	4.06"	1.81"	

Crosses

Run Size	Working Pressure	Outlet Size	Working Pressure	A	B	C	D	Part Number
2-1/16"	5,000	2-1/16"	5,000	4.50"	4.50"	2.06"	2.06"	
2-9/16"	5,000	2-1/16"	5,000	4.50"	5.00"	2.56"	2.06"	
2-1/16"	10,000	1-13/16"	10,000	4.38"	4.38"	2.06"	1.81"	
2-9/16"	10,000	1-13/16"	10,000	4.50"	5.12"	2.56"	1.81"	
4-1/16"	10,000	1-13/16"	10,000	7"	6.875"	4.06"	1.81"	